

Inspection Report

Name of Work : Construction of Graveyard Burial Building at Jakku Village in Ward No. 05, Byatarayanapura Sub Division.

Work Order : EE/BTP/BBMP/E-PMT-01(17846)/WO/190/2015-16 Dated: 03.02.2016.

Agency : A. Krishna Reddy

B.R. No & Date : 39/2015-16 Dated: 31.03.2016

Bill Amount : 14,23,571.00

Job Code : 008-15-000005

P. Code : P-3089

Date of Inspection : 15-06-2016.


The above said work "Construction of Graveyard Burial Building at Jakku village in ward no 05, Byatarayanapura Sub division" was shown to me by the concerned Engineer.


The above said work is inspected & in conformity with the concerned Ward Engineer.

The work done is satisfactory.




MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT





Name of work: → Construction of Graveyard burial building
at Takkur village in w-no:5 B.T. Purasubrah



Signature

AS-03

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಇ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟಲಿಯನ್‌ಪುರ ಉಪ ವಿಭಾಗ

Signature

MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT